



**HESTORE.HU**

elektronikai alkatrész áruház


**EN:** This Datasheet is presented by the manufacturer.

Please visit our website for pricing and availability at [www.hestore.hu](http://www.hestore.hu).

**Circuit to enable the panel meter to measure its own supply voltage**

**LCD Panel Meter  
PM438**

**Product Code:  
375-102**



CIRCUIT TO READ INPUT SUPPLY ON PM-438

**Circuit Function**

The DVM cannot measure its own supply by direct connection of the supply to the measurement input terminals, because both IN+ and IN- inputs sit at approximately 6.3V above the supply 0V.

There are several ways to scale and level-shift the monitored supply voltage. The solution given above, using the *Howland* current source is probably the most economical in components.

The accuracy obtained with typical op-amp offsets and 1% resistors is approximately  $\pm 2\%$ . For improved accuracy, trim R5 to give the correct reading for a known power supply input.

Distributed by:



JPR Electronics Ltd  
Unit 4  
Circle Business Centre  
Blackburn Road  
Houghton Regis  
**Dunstable**, Beds  
LU5 5DD

Tel: 01582 470000  
Fax: 01582 470001

email: [sales@jprelec.co.uk](mailto:sales@jprelec.co.uk)  
website: [www.jprelec.co.uk](http://www.jprelec.co.uk)

## Introduction

This DVM is a 3½ digit panel meter with FSD  $\pm 199.9$  mV, automatic polarity indication, with accuracy  $\pm 0.5\% \pm 1$  digit.

### *Technical Data*

Input impedance	>100M $\Omega$
Accuracy	$\pm 0.5\% \pm 1$ digit
Measurement range	199.9mV
Indication method	LCD display
Measurement method	Dual-slope integration A/D
Power supply	8 — 12V DC (9V battery)
Supply current	$\approx 1$ mA
Operating temperature range	23°C $\pm$ 5°C
Size	68mm x 44mm

### *DC Supply*

The input required is 8 — 12V DC @ 1mA from battery or power supply. Connections are labelled V+ and V-. Check the polarity “+” and “-” before connection.

## General Description

### *Analogue-to-digital Converter*

This panel meter uses a low power CMOS 3½ digit analogue-to-digital converter.

The DC voltage at the input measurement connection (IN-) is approximately +6.3V relative to the negative terminal (V-) of the power supply or battery).


### *Reference Adjustment*

The internal reference is factory-set to give the correct reading for a known voltage applied to the input terminals.


### *Decimal Point*

The decimal point is set by jumpers P1, P2 and P3 (see “How to expand”).

## Multirange Voltmeter Expansion




## Multirange Current Meter Expansion




## How to Expand

To expand the range of voltage to be measured, remove RA (10M $\Omega$ ) and RB (s/c link) from meter PCB and connect external resistors as follows:



To expand the range of current to be measured, use the correct value of shunt resistor R1 as shown below:



Range	R1 (Theoretical value)	R1 (Practical combination)	R2	Fit Jumper link
20V	9.9M $\Omega$	7.5M $\Omega$ + series 2.4M $\Omega$	100k $\Omega$	P2
200V	9.99M $\Omega$	10M $\Omega$	10k $\Omega$	P3
2000V	9.999M $\Omega$	10M $\Omega$	1k $\Omega$	no jumper

Range	R1
0.2mA	1k $\Omega$
2mA	100 $\Omega$
20mA	10 $\Omega$
200mA	1 $\Omega$
2A	0.1 $\Omega$